EnergyPerformanceCertificate

PenyrOdyn ARTHOG LL391AJ Dwellingtype:House
Dateofassessment:27April2007
Dateofcertificate:27April2007

Referencenumber: 2738 -9080-6254-4223-0024


Totalfloorarea:216m ²

Thishome'sperformanceisratedintermsoftheenergyusepersquaremetreoffloorarea,energyefficiency basedonfuelcostsandenvironmentalimpactbasedoncarbondioxide(CO 2) emissions.

EnergyEfficiencyRating Current Potential Veryenergyefficient -lowerrunningcosts (92 to 100) В (81 to 91) (69 to 80) (55 to 68) (39 to 54) (21 to 38) 29 16 G (1 to 20) Notenergyefficient -higherrunningcosts **EUDirective** England&Wales 2002/91/EC

Theenergyefficiencyratingisameasureofthe overallefficiencyofahome. The higher the rating, the more energy efficient the home is and the lower the fuelbills will be.

EnvironmentalImpactRating



Theenvironmentalimpactratingisameasureofa home'simpactontheenvironmentintermsofcarbon dioxide(CO ₂) emissions. The higher the rating, the less impact it has on the environment.

Estimatedenergyuse,carbondioxide(CO 2) emissionsandfuelcostsofthishome

	Current	Potential
Energyuse	510kWh/m ² peryear	382kWh/m ² peryear
Carbondioxideemissions	23tonnesperyear	17tonnesperyear
Lighting	£168peryear	£86peryear
Heating	£2441peryear	£1922peryear
Hotwater	£295peryear	£183peryear

Basedonstandardisedassumptionsaboutoccupancy,heatingpatternsandgeographicallocation,theabove tableprovidesanindicationofhowmuchitwillcosttoprovidelighting,heatingandhotwatertothishome. Thefuelcostsonlytakeintoaccountthecostoffuelandnotanyassociatedservice,maintenanceorsafety inspection. This certificate has been provided for comparative purposes only and enables one home to be compared with another. Always check the date the certificate was issued, because fuel prices can increase overtime and energy saving recommendations will evolve.

To see how this home can achieve its potential rating pleases eether ecommended measures.



Remembertolookfortheenergysavingrecommendedlogowhenbuyingenergyefficientproducts. It'saquickandeasywaytoidentifythemostenergyefficientproductsonthemarket. Foradviceonhowtotakeactionandtofindoutaboutoffersavailabletohelpmakeyourhome moreenergyefficientcall0800512012orvisitwww.energysavingtrust.org.uk/myhome



<u>Aboutthisdocument</u>

The Energy Performance Certificate for this dwelling was produced following an energy assessment under taken by a qualified assessor, accredited by the NHERAccreditation Scheme, to ascheme authorised by the Government. This certificate was produced using the RdSAP 2005 assessment methodology and has been produced under the Energy Performance of Buildings (Certificates and Inspections) (England and Wales) Regulations 2007. A copy of the certificate has been lodged on a national register.

Assessor'saccreditationnumber: SAVA001156
Assessor'sname: MrPhilipLockwood
Companyname/tradingname: EPCNorthWales

Address: Ferndale,2TrinitySquare,Llandudno,Conwy,LL302PY

Phonenumber: (01492)868500

Faxnumber:

E-mailaddress: lockwoodp@aol.com

Ifyouhaveacomplaintorwishtoconfirmthatthecertificateisgenuine

Detailsoftheassessorandtherelevantaccreditationschemeareonthecertificate. Youcangetcontact detailsoftheaccreditationschemefromourwebsiteatwww.nher.co.uktogetherwithdetailsoftheir proceduresforconfirmingauthenticityofa certificateandformakingacomplaint.

Aboutthebuilding'sperformanceratings

Theratingsonthecertificateprovideameasureofthebuilding'soverallenergyefficiencyandits environmentalimpact, calculated in accordance with an ational methodology that takes into account factors such as insulation, heating and hot watersystems, ventilation and fuels used. The average energy efficiency rating for adwelling in England and Wales is band E (rating 46).

Notallbuildingsareusedinthesameway, soenergyratingsuse's tandardoccupancy'assumptions which may be different from the specific way you use your building. Different methods of calculation are used for homesand for other buildings. Details can be found a twww.communities.gov.uk/epbd

Buildingsthataremoreenergyefficientuselessenergy,savemoneyandhelpprotecttheenvironment. A buildingwitharatingof 100 would costal most nothing to heat and light and would cause almost no carbon emissions. The potential ratings in the certificated escribehow close this building could get to 100 if all the cost effective recommended improvements were implemented.

Abouttheimpactofbuildingsontheenvironment

Oneofthebiggestcontributorstoglobalwarmingiscarbondioxide. Thewayweuseenergyinbuildings causesemissionsofcarbon. The energyweuse forheating, lighting and power inhomes produce sovera quarter of the UK's carbondioxide emissions and other buildings produce a further one -sixth.

Theaveragehouseholdcausesabout6tonnesofcarbondioxideeveryyear.Adoptingtherecommendations inthisreportcanreduceemissionsandprotecttheenvironment.Youcouldreduceemissionsevenmoreby switchingtorenewableenergysources.Inadditiontherearemanysimpleeverydaymeasuresthatwillsave money,improvecomfortandreducetheimpactontheenvironment,suchas:

- Checkthatyourheatingsystemthermostatisnotsettoohigh(inahome,21 °Cinthelivingroomis suggested)andusethetimertoensurethatyouonlyheatthebuildingwhennecessary.
- Makesureyourhotwaterisnottoohot acylinderthermostatneednotnormallybehigherthan60 °C
- Turnofflightswhennotneededanddonotleaveappliancesonstandby.Remembernottoleave chargers(e.g.formobilephones)turnedonwhenyouarenotusingthem.

VisittheGovernment'swebsiteatwww.communities.gov.uk/epbdto:

- Findouthowtoconfirmtheauthenticityofanenergyperformancecertificate
- Findhowtomakeacomplaintaboutacertificateortheassessorwhoproducedit
- Learnmoreaboutthenationalregisterwherethiscertificatehasbeenlodged
- Learnmoreaboutenergyefficiencyandreducingenergyconsumption.



Recommendedmeasurestoimprovethishome's energy performance

PenyrOdyn ARTHOG LL391AJ Dateofcertificate:27April2007 Referencenumber:21962

Summaryofthishome'senergyperformancerelatedfeatures

The following is an assessment of the key individual elements that have an impact on this home 's performance rating. Each element is assessed against the following scale: Very poor/Poor/Average/Good/Very good.

Element	Description	Currentper	Currentperformance	
	Description	EnergyEfficiency	Environmental	
Wall	Graniteorwhinstoneasbuilt,noinsulation	Verypoor	Verypoor	
Roof	Pitchedroof,noinsulation	Verypoor	Verypoor	
Floor	Uninsulatedsolidconcrete(assumed)	-	-	
Windows	Doubleglazed	Good	Good	
Mainheating	Oilboiler	Poor	Poor	
Mainheatingcontrols	Programmer,roomthermostatandTRVs	Average	Average	
Secondaryheating	Electricfire	Verypoor	Poor	
Hotwater	Frommainsystem	Poor	Verypoor	
Lighting	5%oflightingprovidedbylow -ebulbs	Verypoor	Verypoor	
Currentenergyeffici	encyrating	G:16		
Currentenvironmen	talimpact(CO ₂)rating		G:15	



Recommendations

Themeasures below are cost effective. The performance ratings after improvement listed below are cumulative, that is they assume the improvements have been installed in the order that they appear in the table.

Lowercostmeasures	Typicalsavings	Performanceratingsafterimprovements		
(upto £500)	peryear	Energyefficiency	Environmentalimpact	
Replaceallnon -low-energylightbulbs	£48peryear	G:17	G:15	
Sub-total	£48peryear			
Highercostmeasures				
Installcylinderthermostat	£188peryear	G:20	G:18	
Upgradeexistingoilboilertocondensingboiler	£477peryear	F:29	F:27	
Total	£713peryear			
Potentialenergyefficiencyrating F:29				
Potentialenvironmentalimpact(CO ₂)rating			F:27	

Furthermeasurestoachieveevenhigherstandards

The further measures listed below should be considered in addition to those already specified if a iming for the highest possible standards for this home.

Fit50mminternalinsulationtowall	£805peryear	E:50	E:45
Addaphotovoltaicsystem(25%ofroof)	£43peryear	E:52	E:47
Enhancedenergyefficiencyrating		E:52	
Enhancedenvironmentalimpact(CO 2)rating		E:47

Improvementstotheenergyefficiencyandenvironmentalimpactratingswillusuallybeinstepwitheach other. However, they can sometimes diverge because reduced energy costs are not always accompanied by a reduction in carbon dioxide (CO 2) emissions.



About the cost effective measures to improve this home 'sperformance ratings

Lowercostmeasures(typicallyupto £500each)

These measures are relatively in expensive to install and are worth tackling first. Some of them may be installed as DIY projects. DIY is not always straightforward and sometimes there are health and safety risks, so take advice before carrying out DIY improvements.

Replaceallnon -low-energylightbulbs

Replacementoftraditionallightbulbswithenergysavingrecommendedoneswillreducelightingcostsover thelifetimeofthebulb,andtheylastupto12timeslongerthanordinarylightbulbs.Alsoconsiderselecting lowenergylightfittingswhenredecorating;contacttheLightingAssociationforyourneareststockistof DomesticEnergyEfficientLightingSchemefittings.

Highercostmeasures(typicallyover £500each)

Installcylinderthermostat

Ahotwatercylinderthermostatenablestheboilertoswitchoffwhenthewaterinthecylinderreachesthe requiredtemperature; thisminimisestheamountofenergythatisusedandlowersfuelbills. The thermostat is temperatures ensorthat sends a signal to the boiler when the required temperature is reached. To be fully effective it needs to be sited in the correct position and hardwired in place, so it should be installed by a competent plumber or heating engineer.

Upgradeexistingoilboilertocondensingboiler

Acondensingboileriscapableofmuchhigherefficienciesthanothertypesofboiler,meaningitwillburn lessfueltoheatthisproperty. Thisimprovementismostappropriatewhentheexistingcentralheatingboiler needsrepairorreplacement, but the remay be exceptional circumstances making this impractical. Condensing boilers need a drainforthe condensate which limits their location; remember this when considering remodelling the room containing the existing boiler even if the latter is to be retained for the time being (for examplea kitchen make over). Building Regulations apply to this work, so your local authority building control departments hould be informed, unless the installer is registered with a competent persons scheme {1}, and can therefore self -certify the work for Building Regulation compliance. Askaqualified heating engineer to explain the options.

Aboutthefurthermeasurestoachieveevenhigherstandards

Furthermeasuresthatcoulddeliverevenhigherstandardsforthishome

Fit50mminternalinsulationtowall

Solidwallinsulationinvolvesaddingalayerofinsulationtoeithertheinsideortheoutsidesurfaceofthe externalwalls, which reduces heatloss and lowers fuelbills. A sitis relatively expensive it is only recommended forwalls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry -lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is be stapplied when rooms require redecorating and can be installed by a competent DIY enthusiast. External solid wall insulation is the application of an insulant and a weather - protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide long - lasting weather protection. The External Wall Insulation Association keeps a register of professional installers. It should be noted that planning permission might be required.

Addaphotovoltaicsystem(25%ofroof)

AsolarPVsystemisonewhichconvertslightdirectlyintoelectricityviapanelsplacedontheroofwithno wasteandnoemissions. Thiselectricityisusedthroughoutthehomeinthesamewayastheelectricity purchasedfromanenergysupplier. The Solar Trade Association has up -to-date information on local installers who are qualified electricians and any grant that may be available. Planning restrictions may applyincertainne ighbourhoods and you should check this with the local authority. Building Regulations apply to this work, so your local authority building control departments hould be informed, unless the installer is registered with a competent persons scheme {1}, and can therefore self -certify the work for Building Regulation compliance. Askasuitably qualified electrician to explain the options.

